

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Dee C. Hansen Executive Director Dianne R. Nielson, Ph.D. Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340



0023

July 21, 1988

TO:

John Whitehead, Permit Supervisor

FROM:

Richard V. Smith, Geologist RVS

RE:

Review of Recompiled PAP, Co-Op Mining Company, Bear Canyon

Mine, ACT/015/025, Folder #2, Emery County, Utah

The recompiled Bear Canyon PAP continues to suffer from a lack of consistency and the incorporation of irrelevant and redundant information. I suggest that the following portions of the recompiled PAP be deleted to provide a more concise, consistent and functional PAP.

## Deletions

- First paragraph of Section 3.3.5, p. 3-7.
- Section 3.3.14.2, p. 3-15.
- Parts "a. Roof Control" (p.3-21 and 3-22) and "d. Electrical" (p. 3-23 and 3-24) of Section 3.4.1.5. Remove "Roof Control" and "Electrical" from the title of Section 3.4.1.5, p. 3-21.
- Section 3.4.3.2, p. 3-29.
- Second paragraph of Section 3.4.3.2.1, p. 3-29.
- Section 3.4.3.2.3, p. 3-37 and 3-38. 6.
- Section 3.4.3.2.4, p. 3-38. 7.
- Section 3.4.3.2.5, p. 3-38 Section 3.4.4, p. 3-39. 8.
- 9.
- 10.
- Section 3.4.5.2, p. 3-40 Section 3.4.6.4.3 p. 3-47 11.
- Section 3.4.6.4.6, p. 3-48 12.
- Section 3.4.7, p. 3-48 and 3-49. 13.
- 14. Figure 3-4, p.  $\bar{3}$ -51.
- 15. First paragraph in section 3.5.3.1, p. 3-59.
- 16. Section  $3.\overline{5}.3.4$ , p. 3-62.

17. Table 3-6, p. 3-64.

Entire p. 3-65. 18.

- 19. Section 3.5.8, p. 3-81 and 3-82.
- Section  $3.5.8.\overline{1}$ , p. 3-82 and 3-83. 20.
- Section 3.5.8.2, p. 3-83 and 3-84. 21.
- Section 3.5.8.3, p. 3-84 and 3-85. 22.

23. Section 3.5.9.1, p. 3-86.

Appendix 3-B, p.3-144 through 3-155. 24.

25. Section  $4.4.2.\overline{5}$ , p. 4-13.

Section 4.4.2.5.1, p. 4-14. 26.

- 27.
- Section 4.4.2.5.2, p. 4-14 and 4-15. Portion of p. 4-15 entitled "Minerals." 28.
- 29. Section 4.4.2.5.3, p. 4-15.

30. Section 4.5.3, p. 4-22.

- 31. Portion of p. 4-24 entitled "Ground Water," including subsections entitled "Management Objective" and "Impacts."
- 32. Portion of p. 4-29 entitled "Wilderness Roadless Areas," including subsections entitled "Management Objective" and "Impacts (p. 4-30)."
- 33. Table 4-4, p. 4-37.
- Figure\_1, p. 6-22. 34.
- 35. Table 7.1- $\bar{1}$ , p. 7-21.
- Table 7.1-2, p. 7-22. 36.
- 37. Appendix 7-A.

In addition to the above-identified deletions, I suggest that the below-listed items be corrected or incorporated into the PAP.

Chapter 7 requires page numbers.

- Section 7.1 of Chapter 7, entitled "Groundwater Hydrology," will require a groundwater monitoring plan that explicitly lists groundwater monitoring stations shown on Plate 7-1 and identifys water quality parameters and monitoring frequencies that are in accordance with the Division Water Monitoring Guidelines (see Tables 3 and 4). see section 7.1.7, p. 20 through 21A and in particular, the first paragraph on p. 21 and the last paragraph on p.21-A of the approved PAP.
- Change 100 foot value in first sentence on P. 1-5 to "200 feet."

Page 3 WPP40/1-3

- 4. Change reference to Section 3.4.3.3. in second sentence on p. 3-60 to "Chapter 7."
- 5. Page 3-63 appears to be missing text.

## Conclusion

I urge that as other staff review this recompiled PAP they also identify redundant and irrelevant material for deletion from the PAP.

## RVS/cl

cc: P. Grubaugh-Littig

T. Munson

B. Stettler

WPP40/1-2